

**New KRONOS (KRONOS 2) 61/73/88**

**Sub-System Version 1.08 (V01R08)**

June 26, 2015

Note: Sub-System Version 1.08 (V01R08) is only available for the New KRONOS (KRONOS 2) production model. It can NOT be used for the KRONOS and KRONOS X production models.

## **Changes**

- In rare case, when using USB MIDI data dump or USB audio between the new KRONOS and an external computer, noises or glitches might have occurred on KRONOS audio output signals. This has now been fixed.
- In rare case, during normal operation, an operational error might have occurred by displaying the following message. "A problem has been detected, which may have been caused by cycling power too quickly. " This has now been fixed.